

**CERTIFICATE**

This is to certify that, the actual building of Radcliffe School, Plot No.3, Sector-8, Kharghar, Navi Mumbai, was inspected on 10/012020. Generally external area of building found to be in good condition. Also, no major structural disturbances were observed in the interior inspection of the building. No rust or settlement was found in the columns, trunks, ladders, etc. of the building. In general, the building was found to be good condition.

sd/-

Assistant Engineer Category-1  
C.B. Subsection No. 1,  
Panvel




sd/-

Executive Engineer  
Public Works Department  
Panvel

JA.KRA.SA.BAN.VI / Panvel / Resha/ 203  
Executive Engineer's Office,  
S.B. Department, Office,  
Date:10/01/2020

Translated from Marathi  
To English by me


  
Adv. Swati Palande  
Mrs. Swati Palande  
(B.A., LL.B.)  
ADVOCATE HIGH COURT  
22 Prabhakar Center, Sec-1A,  
CBD-Belapur, Navi Mumbai




प्रमाणपत्र

प्रमाणित करण्यांत येते की रेडक्लीफ स्कूल, प्लॉट नं.३, सेक्टर -८, खारघर, नवी मुंबई या शाळेच्या इमारतीची दिनांक १०/०१/२०२० रोजी प्रत्यक्ष पहाणी केली असता सदर इमारतीचा बाहेरील गिळावा सर्वसाधारणतः सुस्थितीत आढळला. तसेच इमारतीचे आतील पहाणीत कोणतेही मोठे स्ट्रक्चरल डिस्ट्रेस दिसून आले नाहीत. इमारतीचे स्तंभ, तुळ्या, लादया इत्यादींमध्ये कोणतेही रस्ट, सॅग, अथवा सटेलमॅट आढळून आले नाहीत. सर्वसाधारणपणे सदर इमारत सुस्थितीत आढळून आली.



  
सहाय्यक अभियंता श्रेणी-१  
सा.बां. उपविभाग क्र.१,  
पनवेल.

  
कार्यकारी अभियंता  
सार्वजनिक बांधकाम विभाग  
पनवेल.

जा.क्र. सा.बां.वि/पनवेल/रेशा/२०३  
कार्यकारी अभियंता यांचे कार्यालय,  
सा.बां.विभाग, कार्यालय,  
दिनांक. १०/०१/२०२०

